







Installation and User Instructions

TRIAX UFO 170


Active digital antenna FM / DAB / DAB+ / BIII / UHF

Model		Item no.		
TRIAX UFO	170	109170		
Version	891022B	01 - 2020	DK FN DF SF FR	

triax.com




Connection cable and assembly




Use Class A or A+ high shielded coaxial cable only.

Mount UFO on base





D: Secure with enclosed screws





Mounting options on vertical or horizontal surface






Positioning the antenna:

Assemble brackets and desk mount.


Positioning the antenna and mark off holes for fixing.

Mounting on mast.






Mounting with universal mount



Mounting with centre mount (optional accessory for UFO 170)



Positioning the antenna:

Centre mounting bracket and deckmount. Position the antenna and mark off holes for fixing. Positioned antenna and counter nut fixed.

UFO 170 digital antenne Mounting instruction





Troubleshooting guide


Problem	Possible root cause	Solution
Weak or missing signal Often this is caused by a short or a missing connection in the coax cable or the cable connectors.		Remove the cable from the PSU/ power inserter. If the LED lights up, there is a short in the cable. Repair or replace the cable.
	Check LED on PSU/power inserter (optional accessory IFP XXX)	If the LED lights up on the PSU/ power inserter but not on the UFO, there is possibly a missing connection in the cable or connectors.
	Check LED on UFO antenna	If the LED is still on, repair or replace cable and/or connectors.
		If the LED is still off, replace the PSU/power inserter.
Interference	Interference is often caused by electronic equipment – mobile phones, computers, tablets or transmitters being used in close proximity to the UFO.	Increase the distance to the interfering source of possible. Increase the height of the UFO in order to improve signal reception.
Pixelation and missing audio	Pixelation and missing audio is often caused by electronic equipment – mobile phones, computers, tablets or transmitters being used in close proximity to the UFO.	Increase the distance to the interfering source of possible. Increase the height of the UFO in order to improve signal reception.
Ghosting; double pictures (analog signal only)	Ghosting is caused by the TV signal being reflected from buildings, large ships etc.	Change position a few meters will often solve the problem.




Application examples











Technical data

Туре			UFO 170 Digital	
Art. No.			109170	
Frequency ran	ge FM DAB/VHF UHF	MHz MHz MHz	87.5-108 174-300 470-694	
Channels			FM/DAB/DAB+/5-12/21-48	
Elements		stk.	1	
Opening angle	ver./hor.	deg.	90/360	
Windload		N	5.5	
Gain	VHF/UHF	dB	28/27	
Noise figur		dB	3.0	
Max. output voltage VHF/UHF		dΒμV	107/104	
Supply voltage	•	V	5-24	
Power consum	nption	mA	45	
Dimensions	length width height	mm mm mm	325 255 65	
Connector			F-conn	
Included			Mast bracket Ø25-60 Plastic base Universal mount	

Accessories



IFP 502 / IFP 124 Power supply Art. No. 339502 / 339124



IFP 522 / IFP 224 Power supply/-inserter 339522 / 339224



Centre mount Art. No. 133225



For further information and updated manuals go to

triax.com/support







